

MSA | MS | MAV | PA | SW | SV

Magnetic Welding Angles

Your universal magnetic "henchman" for welding and assembly works. All magnetic angles are switchable and suitable for flat and round material. Only SW and SV 100 are not switchable.

SV 100, MAV 120 and PA 200 are stepless adjustable angles.



MS



SW



SV 100



MAV 120



PA 200



MSA

Features

- ✔ Easy positioning, adjusting and fixing of workpieces
- ✔ No deflection or influence of welding arc
- ✔ The contact areas of MS, MAV 120 and PA 200 are separately switchable
- ✔ The angle of MAV120 and PA200 have a light and accurate angle adjustment by quick release and scale



| Technical data | Dimensions | Angle | Switchable | Use also for round material | Adhesive force | Weight | No. | Price |
|----------------|---------------------|------------|------------|--------------------------------|----------------|--------|-------|--------|
| | [L×W×H] [mm] | | | | | | | |
| MSA I | 110 x 30 x 95 | 45°/90° | Yes | Yes | 40 | 0,7 | 45338 | 54,00 |
| MSA II | 150 x 35 x 130 | 45°/90° | Yes | Yes | 75 | 1,4 | 45339 | 68,00 |
| MS 2-80 | 153 x 38 x 153 | 90° | Yes * | Yes | 55 | 1,2 | 48192 | 130,00 |
| MS 2-90 | 195 x 46 x 195 | 90° | Yes * | Yes | 120 | 2,7 | 18736 | 170,00 |
| MAV 120 | 197 x 50 x 197 | 30° - 275° | Yes * | Yes | 50 | 2,4 | 162 | 190,00 |
| PA 200 | 240 x 41 x 240 | 22° - 270° | Yes * | Yes | 90 | 1,6 | 60343 | 197,00 |
| SW 200 | 200 x 50 x 200 | 90° | No | No | 40 | 2,5 | 46504 | 110,00 |
| SW 300 | 300 x 50 x 300 | 90° | No | No | 60 | 4,0 | 46503 | 130,00 |
| SV 100 | 190 x 50 + 150 x 50 | 30° - 270° | No | No | 100 | 2,0 | 22318 | 130,00 |

* Every thigh is separately switchable

Prices are subject to change